



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: August 21, 2008

Reviewed: LK

Mine Name: RLR Site #4	Permit Number: S0470095
Operator Name: Red Leaf Resources, inc.	Inspection Date: 08/19/2008
Inspector(s): Brett Gregory (for Leslie Heppler)	Time: 1:00 pm
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$22,300 **Permit fee:** is current

Purpose of Inspection: This was a first inspection of the site, routine annual inspection. No mining has commenced as of yet.

Inspection Summary: see attached photos

3. Ponding water shown in the pictures is pre-existing. The drainage is already eroded quite a bit

Conclusions and Recommendations: Nothing to note of any significance. DOGM to continue to monitor this site.


Inspector's Signature

LAH:BG:pb

cc: Red Leaf Resources, Inc. – James Patten
(SITLA – John Blake)

O:\M047-Utah\S0470095-RLR4\inspections\ins-08192008_S0470095.doc


0005




Ponding water.



Existing erosion.



Plant vegetation.



Lower view of what has already eroded.